



pin	1	2	3	4	5	6	7	8	9	10
Name	Vcc					RA-	DEC-	DEC+	RA+	GND



Connect the solder jumper to select internal 5V on pin1

ST4 interface



Interconnect Freego2 with ST4 interface

